

# PRICE LIST – GREEN WOLF

Indicative prices 2017

**The cost of repairs includes :**

- Labor cost
- Product repair
- Basic consumables (thread, heat-activated adhesive and accessories)

**Not included :**

- Logistics cost

Type of repair	Prices Exclusive of taxes	Prices Inclusive of taxes
<b>TEAR, HOLE, WEAR SOLUTIONS</b>		
<b>TEAR REPAIRS</b> <i>From</i>		
Transparent patch	5,83	7,00
Patch with lining	8,33	10,00
Lining seam	15,00	18,00
Patch or seam requiring the setting of an inside patch	+5,83 on prices above	+7,00 on prices above
Ski-edge protection change	25,00	30,00
<b>VELCRO REPLACEMENT</b> <i>From</i>		
Crossing Velcro	8,33	10,00
Invisible Velcro	15,00	18,00
<b>RESTITCHING</b> <i>From</i>		
Simple restitching	5,83	7,00
Complex restitching	10,00	12,00
<b>ZIP, SLIDER, SNAP-BUTTON REPLACEMENT</b>		
<b>ZIP REPLACEMENT</b> <i>From</i>		
Standard pocket zip	22,50	27,00
Watertight pocket zip	30,00	36,00
Express central zip	20,83	25,00
Standard central zip	40,00	48,00
Watertight central zip	50,00	60,00

Central zip on down-filled jacket	50,00	60,00
<b>SLIDER REPLACEMENT</b>		
<i>From</i>		
Standard slider	8,33	10,00
Watertight slider	16,67	20,00
<b>SNAP-BUTTON REPLACEMENT</b>		
<i>From</i>		
Crossing snap-button	8,33 for the 1 <sup>st</sup> one, then 4,17 for the others if no tool replacement is required	10,00 for the 1 <sup>st</sup> one, then 5,00 for the others if no tool replacement is required
Ordinary snap-button	8,33	10,00
<b>WATER-REPELLENT TREATMENT</b>		
<i>From</i>		
Washing +new water-repellent treatment	12,50	15,00
<b>BACKPACK AND TENT REPAIRS</b>		
Contact us for an estimate		

